## CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date 20150508-SA10300 SA10300-19970328 2015-MAY-08

PFANNENBERG GMBH
WERNER-WITT-STRASSE 1
POSTFACH 80 07 47
21007 HAMBURG GERMANY

This is to certify that representative samples of

COMPONENT - AIR CONDITIONERS, SPECIAL PURPOSE See next page for models.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 1995/CSA C22.2 No 236, Standard for Heating and

Standard(s) for Safety:

Additional Information:

Cooling Equipment See the UL Online Certifications Directory at

CAN/CSA C22.2 No. 117, Standard for Room Air

UL 484, Standard for Room Air Conditioners

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Conditioner

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.

Barnely

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>

## **CERTIFICATE OF COMPLIANCE**

**Certificate Number Report Reference Issue Date**  20150508-SA10300 SA10300-19970328 2015-MAY-08

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Special Purpose Air Conditioners

TEP resents Btu/h.)   DTD 5101 DTT 3500   DTD 5201 DTT 4500   DTD 5301 DTT 6500   DTD 5501 DTS 3141
DTD 5301 DTT 6500 DTD 5501
DTD 5501
DIS 3141
DTS 3161 DTS 3181
DTS 3241
DTS 3261
DTS 3281
DTS 7001 -
DTS 7041 DTS 1200
DTS 7061 DTS 2000/DTS 2000 NEMA
DTS 7101 DTS 3500
DTS 7141/1 -
DTS 7171, 7151 - DTS 7241 DTS 5000
DTS 7301 -
DTS 7341 DTS 6000
DTS 7441 DTS 8000
DTS 7541 DTS 10000
DTS 7451
- DTS 12000
- DTI 9221 PLL 800
PLL 350
PLL 4223 PLL 4223
PLL 4123 PLL 4123
DTI 800
DTI 1400
DTI or DTS f/by 9031
DTI or DTS f/by 9031H
DTI or DTS f/by 9041
DTI or DTS f/by 9141

DTI or DTS f/by 9141 DTI or DTS f/by 9241

Barnelly

Bruce Mahrenholz, Director North American Certification Program UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, p contact a local UL Customer Service Representative at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>

## CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date 20150508-SA10300 SA10300-19970328 2015-MAY-08

DTI or DTS f/by 9341 DTI or DTS f/by 9341C DTI or DTS f/by 9441 DTI or DTS f/by 9541 DTI or DTS f/by 9841 DTI 9221 PLL 4203 PLL 4213 PLL 4136 DTI or DTFI f/by 9021 DTI or DTFI f/by 9021 CM DTS 9011H

DTI 9221 (230 V)

Barnelly

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>